


## Replacement of the web guide amplifier's battery

Although, the service life of the web guide amplifier's battery will depend on the mode in which the equipment is used, a replacement should be performed every 2 or 3 years. Ensure that the correct type of battery -- i.e., MZ1706.0 -11 -- is used for replacement.



Main board (Preamplifier)